



be undesirable to “mechanically scuff” fiberglass reinforced plastic because that would expose and damage the fiberglass fibers. Therefore, the “knurled or roughened” surface of Wyler must be molded-in, which as noted is discernible from “mechanically scuffing.”

**CLOSING**

For the reasons set forth above, the final rejection of all claims is improper and should be reversed.

Respectfully submitted,

/John E. Carlson/

John E. Carlson, Reg. No. 37,794  
Carlson, Gaskey & Olds PC  
400 W. Maple Rd., Suite 350  
Birmingham, MI 48009  
(248) 988-8681

Dated: November 16, 2009